

CHANGE IN THE SLACK ADJUSTERS IN RIGID TRUCK REAR AXLES

- 1. Change:** The automatic slack adjusters have been changed in the 2005 model year rigid truck axles. The manufacturer of the new slack adjusters is SBT compared to the earlier slack adjusters made by Haldex. In the new design the washers installed both sides of a slack adjuster are now 1.5 mm (0.059") thick compared to 3 mm(0.118") in the old design.
- 2. Cause of Change:** Product standardization.
- 3. Applications:** The new slack adjusters have been taken in production on the following axle types: FRDP-13/16-S, FRMP-13/16-S and FRFP-13/16-S.
- 4. Changed Items :**

Length mm	Offset mm	Side	Earlier Slack Adjusters		Replacing Slack Adjusters	
			Sisu P/N	Haldex P/N	Sisu P/N	SBT P/N
145	56/60	RH	146-530-1011	72938	546-530-1312	14653
145	56/60	LH	146-530-1021	72937	546-530-1322	14654
145	56/60	RH	146-530-1311	79003	546-530-1312	14653
145	56/60	LH	146-530-1321	79002	546-530-1322	14654
165	75	LH	546-530-2011	79396	546-530-2022	14882
165	75	RH	546-530-2021	79397	546-530-2012	14881
165	75	LH	546-530-3411	79662	546-530-2022	14882
165	75	RH	546-530-3421	79663	546-530-2012	14881
165	56/60	LH	546-530-3111	79407	546-530-3122	14830
165	56/60	RH	546-530-3121	79408	546-530-3112	14829

Description	Old Part No.	New Part No.
Washer	91726-43065	090-354-3030

- 5. Date of Change:** Installing of the new SBT made slack adjuster has started gradually by axle type from August 2004 (Mainly in the new model year 2005 axles).
- 6. Interchangeability:** In spare part use a Haldex slack adjuster can be replaced by a SBT slack adjuster according to the table above. Simultaneously the old 3 mm thick washers (one on each side of a slack adjuster) have to be replaced by the new 1.5 mm thick washers.
- 7. Installing the SBT Slack Adjuster:**



